

# Continental

# dekklåven

## Continental dekk 2020

## Nettopris:

Dimensjon

Type

### Continental TractorMaster

440/65 R 24	65 km/t	131 D	TractorMaster	TL	5200,-
480/65 R 24	65 km/t	133 D	TractorMaster	TL	6100,-
540/65 R 24	65 km/t	140 D	TractorMaster	TL	7100,-
440/65 R 28	65 km/t	131 D	TractorMaster	TL	5700,-
480/65 R 28	65 km/t	136 D	TractorMaster	TL	6500,-
540/65 R 28	65 km/t	142 D	TractorMaster	TL	8700,-
600/65 R 28	65 km/t	154 D	TractorMaster	TL	12200,-
600/70 R 28	65 km/t	157 D	TractorMaster	TL	15000,-
540/65 R 30	65 km/t	143 D	TractorMaster	TL	8800,-
600/65 R 30	65 km/t	149 D	TractorMaster	TL	11000,-
600/70 R 30	65 km/t	152 D	TractorMaster	TL	15800,-
710/55 R 30	65 km/t	159 D	TractorMaster	TL	18200,-
710/60 R 30	65 km/t	162 D	TractorMaster	TL	17400,-
750/55 R 30	65 km/t	162 D	TractorMaster	TL	19900,-
540/65 R 34	65 km/t	152 D	TractorMaster	TL	9600,-
600/65 R 34	65 km/t	151 D	TractorMaster	TL	11900,-
650/65 R 34	65 km/t	161 D	TractorMaster	TL	15800,-
540/65 R 38	65 km/t	147 D	TractorMaster	TL	10600,-

<b>600/65 R 38</b>	65 km/t	153 D	<b>TractorMaster</b>	TL	<b>13800,-</b>
<b>650/65 R 38</b>	65 km/t	157 D	<b>TractorMaster</b>	TL	<b>18400,-</b>
<b>650/75 R 38</b>	65 km/t	169 D	<b>TractorMaster</b>	TL	<b>25900,-</b>
<b>650/85 R 38</b>	65 km/t	173 D	<b>TractorMaster</b>	TL	<b>30500,-</b>
<b>710/70 R 38</b>	65 km/t	171 D	<b>TractorMaster</b>	TL	<b>26900,-</b>
<b>800/70 R 38</b>	65 km/t	178 D	<b>TractorMaster</b>	TL	<b>36900,-</b>
<b>900/60 R 38</b>	65 km/t	178 D	<b>TractorMaster</b>	TL	<b>37900,-</b>
<b>650/65 R 42</b>	65 km/t	158 D	<b>TractorMaster</b>	TL	<b>19500,-</b>
<b>710/70 R 42</b>	65 km/t	173 D	<b>TractorMaster</b>	TL	<b>33900,-</b>
<b>710/75 R 42</b>	65 km/t	175 D	<b>TractorMaster</b>	TL	<b>38000,-</b>

## Continental Tractor 70

<b>320/70 R 24</b>	65 km/t	116 D	<b>Tractor 70</b>	TL	<b>3700,-</b>
<b>360/70 R 24</b>	65 km/t	122 D	<b>Tractor 70</b>	TL	<b>4350,-</b>
<b>380/70 R 24</b>	65 km/t	125 D	<b>Tractor 70</b>	TL	<b>4500,-</b>
<b>420/70 R 24</b>	65 km/t	130 D	<b>Tractor 70</b>	TL	<b>5200,-</b>
<b>480/70 R 24</b>	65 km/t	138 D	<b>Tractor 70</b>	TL	<b>6700,-</b>
<b>380/70 R 28</b>	65 km/t	127 D	<b>Tractor 70</b>	TL	<b>5500,-</b>
<b>420/70 R 28</b>	65 km/t	133 D	<b>Tractor 70</b>	TL	<b>6000,-</b>
<b>480/70 R 28</b>	65 km/t	140 D	<b>Tractor 70</b>	TL	<b>7100,-</b>
<b>420/70 R 30</b>	65 km/t	134 D	<b>Tractor 70</b>	TL	<b>7450,-</b>
<b>480/70 R 30</b>	65 km/t	141 D	<b>Tractor 70</b>	TL	<b>7800,-</b>
<b>480/70 R 34</b>	65 km/t	143 D	<b>Tractor 70</b>	TL	<b>8900,-</b>
<b>520/70 R 34</b>	65 km/t	148 D	<b>Tractor 70</b>	TL	<b>10500,-</b>
<b>480/70 R 38</b>	65 km/t	145 D	<b>Tractor 70</b>	TL	<b>10400,-</b>
<b>520/70 R 38</b>	65 km/t	150 D	<b>Tractor 70</b>	TL	<b>11500,-</b>
<b>580/70 R 38</b>	65 km/t	155 D	<b>Tractor 70</b>	TL	<b>15000,-</b>

## Continental Tractor 85

<b>280/85 R 24</b>	115 A8	112 B	<b>Tractor 85</b>	<b>TL</b>	<b>2900,-</b>
<b>320/85 R 24</b>	122 A8	119 B	<b>Tractor 85</b>	<b>TL</b>	<b>3400,-</b>
<b>340/85 R 24</b>	125 A8	122 B	<b>Tractor 85</b>	<b>TL</b>	<b>3500,-</b>
<b>380/85 R 24</b>	131 A8	128 B	<b>Tractor 85</b>	<b>TL</b>	<b>4600,-</b>
<b>420/85 R 24</b>	137 A8	134 B	<b>Tractor 85</b>	<b>TL</b>	<b>5400,-</b>
<b>280/85 R 28</b>	118 A8	115 B	<b>Tractor 85</b>	<b>TL</b>	<b>3350,-</b>
<b>320/85 R 28</b>	124 A8	121 B	<b>Tractor 85</b>	<b>TL</b>	<b>3800,-</b>
<b>340/85 R 28</b>	127 A8	124 B	<b>Tractor 85</b>	<b>TL</b>	<b>4600,-</b>
<b>380/85 R 28</b>	133 A8	130 B	<b>Tractor 85</b>	<b>TL</b>	<b>4900,-</b>
<b>420/85 R 28</b>	139 A8	136 B	<b>Tractor 85</b>	<b>TL</b>	<b>5900,-</b>
<b>380/85 R 30</b>	135 A8	132 B	<b>Tractor 85</b>	<b>TL</b>	<b>5700,-</b>
<b>420/85 R 30</b>	140 A8	137 B	<b>Tractor 85</b>	<b>TL</b>	<b>6450,-</b>
<b>460/85 R 30</b>	145 A8	142 B	<b>Tractor 85</b>	<b>TL</b>	<b>7700,-</b>
<b>380/85 R 34</b>	137 A8	137 B	<b>Tractor 85</b>	<b>TL</b>	<b>6300,-</b>
<b>420/85 R 34</b>	142 A8	139 B	<b>Tractor 85</b>	<b>TL</b>	<b>7300,-</b>
<b>460/85 R 34</b>	147 A8	144 B	<b>Tractor 85</b>	<b>TL</b>	<b>9000,-</b>
<b>340/85 R 38</b>	133 A8	130 B	<b>Tractor 85</b>	<b>TL</b>	<b>5500,-</b>
<b>420/85 R 38</b>	144 A8	141 B	<b>Tractor 85</b>	<b>TL</b>	<b>8500,-</b>
<b>460/85 R 38</b>	149 A8	146 B	<b>Tractor 85</b>	<b>TL</b>	<b>9500,-</b>
<b>520/85 R 38</b>	155 A8	152 B	<b>Tractor 85</b>	<b>TL</b>	<b>12600,-</b>
<b>480/80 R 38</b>	156 A8	156 B	<b>Tractor 85</b>	<b>TL</b>	<b>12000,-</b>
<b>520/85 R 42</b>	162 A8	162 B	<b>Tractor 85</b>	<b>TL</b>	<b>17900,-</b>
<b>480/80 R 46</b>	158 A8	158 B	<b>Tractor 85</b>	<b>TL</b>	<b>13500,-</b>
<b>520/85 R 46</b>	158 A8	158 B	<b>Tractor 85</b>	<b>TL</b>	<b>16100,-</b>

# Servicepriser:

Hjulskift av/på maskin	14"-28"	300,-
	29"-39"	400,-
	40"-52"	500,-
Montering landbruksdekk av/på felg	14"-28"	300,-
	29"-39"	400,-
	40"-52"	500,-
Miljøavgift Landbruksdekk:	14"-28"	400,-
	29"-39"	500,-
	40"-42"	1400,-
Ny-pigging:		6,8
Re-pigging		7,8
Pigging: 24"-30" standard: 168stk Ekstrem: 224stk		
Pigging: 34"--- standard: 192stk Ekstrem: 256stk		
Dekkhottell m/vask Landbruk		2490,-

## Dekklåven AS

Ring 62355020, eller [post@dekklaaven.no](mailto:post@dekklaaven.no)

ALLE PRISER EKSL ARBEID, MILJØ OG MVA